

X17B2 SAFETY CHECKLIST			BROOKHAVEN NATIONAL LABORATORY NATIONAL SYNCHROTRON LIGHT SOURCE
Rev: D	Effective: 7/22/2011	Page 1 of 1	Number: LS-SCL-0038
Prepared by: Philip Marino		Reviewed by: P. Marino	Approved by: B. Chmiel

Original signatures on file.

The only official copy of this file is the one on-line in the NSLS Quality Assurance website. Before using a printed copy, verify that it is the most current version by checking the document effective date on the NSLS QA website.

- 1. Valid Padlock Index and log, no locks open
- 2. X17B2 hutch – threshold door piece (painted yellow) bolted in place under each of 2 doors going into hutch.
- 3. X17B2 hutch – lead shielding mat against threshold door piece in each of 2 doors going into hutch.
- 4. X17B2 hutch interior – water cooled backstop/ Bremsstrahlung shield #4 downstream end of hutch banded and in place (see photo). For X17B2 operation the backstop is in the beam path. For X17B3 operation the backstop is removed from the beam path.
- 5. X17B1 Safety Checklist completed.

OPCO / Beamline Staff: _____ Date: _____

User system check points

- A. Make sure shield is in place on the backside of the Rockland Press.

Users / Beamline Staff: _____ Date: _____